ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
DASARAHALLI

Ward No.
12

Ward Name
Shettihalli

Street ID
W0344

Street Name
NA

Significant Landmark
Shettihalli

Segment No.
12/S-W0344/S123949

Total Length (m)
1111.54

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	1,111.54	77.530637	13.064008	77.520962	13.067045	Shettihalli	Abbigere area and surroundings

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements to drains and asphalting to Abbigeri area and Shettihalli are in ward no. 12

Sanctioned Estimated Amount (Rs.)
1.5

Sanctioned Year
18-19

Year
2018 - 2019

Type of Work
Road

Other Work Type

Tender
Tender

Work Details
Improvements to drains and asphalting to Abbigeri area and Shettihalli are in ward no. 12

Job No. / Work Code
012-18-000015

Work Order No.
301/18-19

Work Order Date
02/02/2019

Period of Extention

Defect Liability Period From
02/02/2019

Defect Liability Period To
05/02/2020

Multiple road involved with the same Job No/ Work Code #
No

Contractor Details

Name of Contractor
M.S.VENKATESH

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)
0.00

Phone No.
9886066040

E-Mail ID

Field Inspection Details

Number of Trees

Any Other Information

Name

Scanned by CamScanner

0

SHIVAKUMAR

Date of Inspection

16/08/2021

Remarks

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.

Scanned by CamScanner

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	CE DAS	07/12/2021	15/09/2021	APPROVED
EE	EE DAS	27/08/2021	15/09/2021	COMPLETED
AEE	Kumarappa H	24/08/2021	15/09/2021	approved
AE	Shivakumar	16/08/2021	15/09/2021	provided
AE	Shivakumar	16/08/2021	15/09/2021	provided

Scanned by CamScanner

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	12	Shettihalli
Street ID	**Street Name**	**Significant Landmark**
W0242	NA	FOREST ROAD
Segment No.	**Total Length (m)**	
12/S-W0242/S012210	707.18	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	707.18	77.517315	13.069661	77.511799	13.072514	ABBIGERE	FOREST ROAD AND SURROUNDING AREA

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to drains and asphalt to Abbigere area shettihali are in ward no. 12	100	2018-19
Year	**Type of Work**	**Other Work Type**
2018 - 2019	Road	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to drains and asphalt to Abbigere area shettihali are in ward no. 12	012-18-000016
Work Order No.	**Work Order Date**	**Period of Extention**
301/18-19.	02/02/2019	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
02/02/2019	05/02/2020	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M.S.VENKATESH		0.00
Phone No.	**E-Mail ID**	
9886066040		

Field Inspection Details

Scanned by CamScanner

Number of Trees	Any Other Information	Name
0		shivakumar
Date of Inspection	**Remarks**	
16/08/2021		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Scanned by CamScanner

Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	CE DAS	07/12/2021	15/09/2021	Approved
EE	EE DAS	27/08/2021	15/09/2021	COMPLETED
AEE	Kumarappa H	24/08/2021	15/09/2021	approves
AE	Shivakumar	16/08/2021	15/09/2021	provided
AE	Shivakumar	16/08/2021	15/09/2021	provided

Scanned by CamScanner